

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Client: Corabar Entertainment		Site: 74 Moorlands		Location: AL7 4QG	
Asset ID: 10164		Description: 10164		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	13/06/2023			Pass	
Overall: Pass					
Asset ID: 10166		Description: LIGHT		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	13/06/2023			Pass	
Earth Current	13/06/2023	25	A	Information	
Earth	13/06/2023	0.06	Ohm	Pass	
Insulation	13/06/2023	>99.99	MOhm	Pass	
Leakage	13/06/2023	<0.1	mA	Pass	
Load	13/06/2023	<0.05	kVA	Information	
Overall: Pass					
Asset ID: 10169		Description: LIGHT		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	13/06/2023			Pass	
Earth Current	13/06/2023	25	A	Information	
Earth	13/06/2023	0.06	Ohm	Pass	
Insulation	13/06/2023	>99.99	MOhm	Pass	
Leakage	13/06/2023	<0.1	mA	Pass	
Load	13/06/2023	<0.05	kVA	Information	
Overall: Pass					
Asset ID: 10170		Description: LIGHT		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	13/06/2023			Pass	
Earth Current	13/06/2023	25	A	Information	
Earth	13/06/2023	0.07	Ohm	Pass	
Insulation	13/06/2023	>99.99	MOhm	Pass	
Leakage	13/06/2023	<0.1	mA	Pass	
Load	13/06/2023	<0.05	kVA	Information	
Overall: Pass					
Asset ID: 10171		Description: LIGHT		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	13/06/2023			Pass	
Earth Current	13/06/2023	25	A	Information	
Earth	13/06/2023	0.06	Ohm	Pass	
Insulation	13/06/2023	>99.99	MOhm	Pass	
Leakage	13/06/2023	<0.1	mA	Pass	
Load	13/06/2023	<0.05	kVA	Information	
Overall: Pass					
Asset ID: 10174		Description: 10174		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	15/05/2023			Pass	
Insulation	15/05/2023	>99.99	MOhm	Pass	
Touch Leakage	15/05/2023	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 10175		Description: 10175		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	15/05/2023			Pass	
Insulation	15/05/2023	>99.99	MOhm	Pass	
Touch Leakage	15/05/2023	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 10196		Description: PSU		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	13/06/2023			Pass	
Insulation	13/06/2023	>99.99	MOhm	Pass	
Touch Leakage	13/06/2023	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 10230		Description: 10230		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	15/05/2023			Pass	
Earth Current	15/05/2023	25	A	Information	

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Earth	15/05/2023	0.05	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Polarity	15/05/2023			Pass

Overall: Pass

Asset ID: 10320	Description: 10320	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10321	Description: 10321	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10329	Description: 10329	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.16	Ohm	Pass
Insulation	05/05/2023	67.81	MOhm	Pass
Polarity	05/05/2023			Pass

Overall: Pass

Asset ID: 10333	Description: 10333	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	<0.04	Ohm	Pass
Insulation	15/05/2023	86.34	MOhm	Pass
Leakage	15/05/2023	<0.1	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10339	Description: 10339	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	<0.04	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	0.16	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10340	Description: 10340	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	<0.04	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	0.13	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10341	Description: 10341	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.04	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	0.13	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10343	Description: Sound Control	User: S JONES	Test Instrument: X22-1286
-----------------	----------------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.07	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	<0.1	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10344	Description: 10344	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10345	Description: 10345	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.05	Ohm	Pass
Insulation	05/05/2023	69.57	MOhm	Pass
Polarity	05/05/2023			Pass

Overall: Pass

Asset ID: 10346	Description: Light Control	User: S JONES	Test Instrument: X22-1286
-----------------	----------------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	<0.04	Ohm	Pass
Insulation	05/05/2023	98	MOhm	Pass
Leakage	05/05/2023	0.67	mA	Pass
Load	05/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10348	Description: Light	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	<0.04	Ohm	Pass
Insulation	05/05/2023	>99.99	MOhm	Pass
Leakage	05/05/2023	0.15	mA	Pass
Load	05/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10349	Description: Light	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	<0.04	Ohm	Pass
Insulation	05/05/2023	>99.99	MOhm	Pass
Leakage	05/05/2023	0.12	mA	Pass
Load	05/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10360	Description: PSU	User: S JONES	Test Instrument: X22-1286
-----------------	------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Insulation	05/05/2023	>99.99	MOhm	Pass
Touch Leakage	05/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10361	Description: 10361	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10363	Description: PSU	User: S JONES	Test Instrument: X22-1286
-----------------	------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Touch Leakage 15/05/2023 <0.1 mA Pass
Overall: Pass

Asset ID: 10386 Description: PSU User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Insulation	05/05/2023	97.03	MOhm	Pass
Touch Leakage	05/05/2023	0.12	mA	Pass

Overall: Pass

Asset ID: 10387 Description: IN EAR MONITOR User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Insulation	05/05/2023	>99.99	MOhm	Pass
Touch Leakage	05/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10389 Description: AC ADAPTER User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Insulation	05/05/2023	>99.99	MOhm	Pass
Touch Leakage	05/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10393 Description: Light User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.06	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	0.11	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10395 Description: LEAD User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.07	Ohm	Pass
Insulation	05/05/2023	57.52	MOhm	Pass
Polarity	05/05/2023			Pass

Overall: Pass

Asset ID: 10405 Description: PSU User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10406 Description: MIXER User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10505 Description: 10505 User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.05	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	<0.1	mA	Pass
Load	15/05/2023	0.23	kVA	Information

Overall: Pass

Asset ID: 10506 Description: 10506 User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Earth	15/05/2023	0.06	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	<0.1	mA	Pass
Load	15/05/2023	0.22	kVA	Information

Overall: Pass

Asset ID: 10507	Description: 10507	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.16	Ohm	Pass
Insulation	05/05/2023	62.76	MOhm	Pass
Polarity	05/05/2023			Pass

Overall: Pass

Asset ID: 10519	Description: 10519	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.09	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	0.13	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10521	Description: 10521	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.14	Ohm	Pass
Insulation	05/05/2023	61.99	MOhm	Pass
Polarity	05/05/2023			Pass

Overall: Pass

Asset ID: 10540	Description: LIGHT	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.05	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	0.26	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10541	Description: LIGHT	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.04	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	0.26	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10554	Description: LEAD	User: S JONES	Test Instrument: X22-1286
-----------------	-------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.04	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Polarity	15/05/2023			Pass

Overall: Pass

Asset ID: 10555	Description: 10555	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.05	Ohm	Pass
Insulation	05/05/2023	68.71	MOhm	Pass
Polarity	05/05/2023			Pass

Overall: Pass

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Asset ID: 10556	Description: SMOKE MACHINE	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	15/05/2023		Pass
Earth Current	15/05/2023	25	A Information
Earth	15/05/2023	0.04	Ohm Pass
Insulation	15/05/2023	9.72	MOhm Pass
Leakage	15/05/2023	<0.1	mA Pass
Load	15/05/2023	0.67	kVA Information
Overall: Pass			
Asset ID: 10576	Description: 10576	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.05	Ohm Pass
Insulation	05/05/2023	53.4	MOhm Pass
Polarity	05/05/2023		Pass
Overall: Pass			
Asset ID: 10581	Description: 10581	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.11	Ohm Pass
Insulation	05/05/2023	65.4	MOhm Pass
Polarity	05/05/2023		Pass
Overall: Pass			
Asset ID: 10610	Description: 10610	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.15	Ohm Pass
Insulation	05/05/2023	67.71	MOhm Pass
Polarity	05/05/2023		Pass
Overall: Pass			
Asset ID: 10612	Description: 10612	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.2	Ohm Pass
Insulation	05/05/2023	69.46	MOhm Pass
Polarity	05/05/2023		Pass
Overall: Pass			
Asset ID: 10613	Description: SPEAKER	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	<0.04	Ohm Pass
Insulation	05/05/2023	98.05	MOhm Pass
Leakage	05/05/2023	<0.1	mA Pass
Load	05/05/2023	<0.05	kVA Information
Overall: Pass			
Asset ID: 10614	Description: SPEAKER	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.04	Ohm Pass
Insulation	05/05/2023	>99.99	MOhm Pass
Leakage	05/05/2023	<0.1	mA Pass
Load	05/05/2023	<0.05	kVA Information
Overall: Pass			
Asset ID: 10616	Description: LIGHT	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	15/05/2023		Pass
Earth Current	15/05/2023	25	A Information
Earth	15/05/2023	<0.04	Ohm Pass

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	0.29	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10617	Description: 10617	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.04	Ohm	Pass
Insulation	05/05/2023	56.01	MOhm	Pass
Polarity	05/05/2023			Pass

Overall: Pass

Asset ID: 10804	Description: SPEAKER	User: S JONES	Test Instrument: X22-1286
-----------------	----------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	<0.04	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	<0.1	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10806	Description: 10806	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.04	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	<0.1	mA	Pass
Load	15/05/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 10811	Description: 10811	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	<0.04	Ohm	Pass
Insulation	05/05/2023	65.93	MOhm	Pass
Polarity	05/05/2023			Pass

Overall: Pass

Asset ID: 10855	Description: 10855	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10856	Description: 10856	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10857	Description: 10857	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Asset ID: 10858	Description: 10858	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Touch Leakage	15/05/2023	<0.1	mA	Pass

Overall: Pass

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Asset ID: 10888	Description: 10888	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	<0.04	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Polarity	15/05/2023			Pass
Overall: Pass				
Asset ID: 10890	Description: 10890	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.04	Ohm	Pass
Insulation	05/05/2023	54.89	MOhm	Pass
Polarity	05/05/2023			Pass
Overall: Pass				
Asset ID: 10895	Description: 10895	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.04	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Leakage	15/05/2023	0.33	mA	Pass
Load	15/05/2023	<0.05	kVA	Information
Overall: Pass				
Asset ID: 10898	Description: 10898	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	<0.04	Ohm	Pass
Insulation	05/05/2023	64.23	MOhm	Pass
Polarity	05/05/2023			Pass
Overall: Pass				
Asset ID: 10899	Description: 10899	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.13	Ohm	Pass
Insulation	05/05/2023	66.98	MOhm	Pass
Polarity	05/05/2023			Pass
Overall: Pass				
Asset ID: 10900	Description: 10900	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.07	Ohm	Pass
Insulation	05/05/2023	62.76	MOhm	Pass
Polarity	05/05/2023			Pass
Overall: Pass				
Asset ID: 10901	Description: 10901	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.08	Ohm	Pass
Insulation	05/05/2023	65.62	MOhm	Pass
Polarity	05/05/2023			Pass
Overall: Pass				
Asset ID: 10903	Description: 10903	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	15/05/2023			Pass
Earth Current	15/05/2023	25	A	Information
Earth	15/05/2023	0.06	Ohm	Pass
Insulation	15/05/2023	>99.99	MOhm	Pass
Polarity	15/05/2023			Pass

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Overall: Pass

Asset ID: 10904	Description: 10904	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	<0.04	Ohm Pass
Insulation	05/05/2023	>99.99	MOhm Pass
Leakage	05/05/2023	<0.1	mA Pass
Load	05/05/2023	<0.05	kVA Information

Overall: Pass

Asset ID: 10917	Description: 10917	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	15/05/2023		Pass
Earth Current	15/05/2023	25	A Information
Earth	15/05/2023	0.07	Ohm Pass
Insulation	15/05/2023	1.45	MOhm Pass
Leakage	15/05/2023	0.3	mA Pass
Load	15/05/2023	1.33	kVA Information

Overall: Pass

Asset ID: 10918	Description: MIXER	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	15/05/2023		Pass
Insulation	15/05/2023	>99.99	MOhm Pass
Touch Leakage	15/05/2023	<0.1	mA Pass

Overall: Pass

Asset ID: 10920	Description: 10920	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.07	Ohm Pass
Insulation	05/05/2023	59.8	MOhm Pass
Polarity	05/05/2023		Pass

Overall: Pass

Asset ID: 10970	Description: 10970	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.39	Ohm Pass
Insulation	05/05/2023	77.72	MOhm Pass
Polarity	05/05/2023		Pass

Overall: Pass

Asset ID: 10971	Description: PSU	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Insulation	05/05/2023	>99.99	MOhm Pass
Touch Leakage	05/05/2023	<0.1	mA Pass

Overall: Pass

Asset ID: 10972	Description: DJ CONTROLLER	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Insulation	05/05/2023	>99.99	MOhm Pass
Touch Leakage	05/05/2023	<0.1	mA Pass

Overall: Pass

Asset ID: 10975	Description: 10975	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	15/05/2023		Pass
Earth Current	15/05/2023	25	A Information
Earth	15/05/2023	0.04	Ohm Pass
Insulation	15/05/2023	>99.99	MOhm Pass
Leakage	15/05/2023	<0.1	mA Pass
Load	15/05/2023	<0.05	kVA Information

Overall: Pass

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Asset ID: 10976	Description: 10975	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	15/05/2023		Pass
Earth Current	15/05/2023	25	A Information
Earth	15/05/2023	0.04	Ohm Pass
Insulation	15/05/2023	>99.99	MOhm Pass
Leakage	15/05/2023	<0.1	mA Pass
Load	15/05/2023	<0.05	kVA Information
Overall: Pass			
Asset ID: 10979	Description: 10979	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	<0.04	Ohm Pass
Insulation	05/05/2023	67.62	MOhm Pass
Polarity	05/05/2023		Pass
Overall: Pass			
Asset ID: 10980	Description: DJ CONTROLLER	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Insulation	05/05/2023	>99.99	MOhm Pass
Touch Leakage	05/05/2023	<0.1	mA Pass
Overall: Pass			
Asset ID: 1099L	Description: 1099L	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.04	Ohm Pass
Insulation	05/05/2023	60.97	MOhm Pass
Polarity	05/05/2023		Pass
Overall: Pass			
Asset ID: 11023	Description: 11023	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.06	Ohm Pass
Insulation	05/05/2023	69.57	MOhm Pass
Polarity	05/05/2023		Pass
Overall: Pass			
Asset ID: 11030	Description: LIGHT CONTROL	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Insulation	05/05/2023	>99.99	MOhm Pass
Touch Leakage	05/05/2023	<0.1	mA Pass
Overall: Pass			
Asset ID: 11031	Description: PSU	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Insulation	05/05/2023	>99.99	MOhm Pass
Touch Leakage	05/05/2023	<0.1	mA Pass
Overall: Pass			
Asset ID: 11032	Description: LIGHT CONTROL	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Insulation	05/05/2023	>99.99	MOhm Pass
Touch Leakage	05/05/2023	<0.1	mA Pass
Overall: Pass			
Asset ID: 11033	Description: PSU	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Insulation	05/05/2023	>99.99	MOhm Pass
Touch Leakage	05/05/2023	<0.1	mA Pass

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Overall: Pass

Asset ID: 11034	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	05/05/2023		Pass
Earth Current	05/05/2023	25	A Information
Earth	05/05/2023	0.07	Ohm Pass
Insulation	05/05/2023	66.2	MOhm Pass
Polarity	05/05/2023		Pass

Overall: Pass

Asset ID: 11035	Description: VOLUME CONTROL	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	13/07/2023		Pass
Earth Current	13/07/2023	25	A Information
Earth	13/07/2023	0.09	Ohm Pass
Insulation	13/07/2023	>99.99	MOhm Pass
Leakage	13/07/2023	<0.1	mA Pass
Load	13/07/2023	<0.05	kVA Information

Overall: Pass

Asset ID: 11036	Description: RACK FAN	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	13/07/2023		Pass
Earth Current	13/07/2023	25	A Information
Earth	13/07/2023	0.05	Ohm Pass
Insulation	13/07/2023	>99.99	MOhm Pass
Leakage	13/07/2023	<0.1	mA Pass
Load	13/07/2023	<0.05	kVA Information

Overall: Pass

Asset ID: 11038	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	13/07/2023		Pass
Earth Current	13/07/2023	25	A Information
Earth	13/07/2023	0.05	Ohm Pass
Insulation	13/07/2023	>99.99	MOhm Pass
Polarity	13/07/2023		Pass

Overall: Pass

Asset ID: 11039	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	13/07/2023		Pass
Earth Current	13/07/2023	25	A Information
Earth	13/07/2023	0.05	Ohm Pass
Insulation	13/07/2023	>99.99	MOhm Pass
Polarity	13/07/2023		Pass

Overall: Pass

Asset ID: 11040	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	13/07/2023		Pass
Earth Current	13/07/2023	25	A Information
Earth	13/07/2023	<0.04	Ohm Pass
Insulation	13/07/2023	>99.99	MOhm Pass
Polarity	13/07/2023		Pass

Overall: Pass

Asset ID: 11041	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	13/07/2023		Pass
Earth Current	13/07/2023	25	A Information
Earth	13/07/2023	0.06	Ohm Pass
Insulation	13/07/2023	>99.99	MOhm Pass
Polarity	13/07/2023		Pass

Overall: Pass

Asset ID: 11042	Description: LIGHT	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	13/07/2023		Pass
Earth Current	13/07/2023	25	A Information

Detailed Latest Test Results

From: 01/01/2023 To: 27/07/2023

Earth	13/07/2023	<0.04	Ohm	Pass
Insulation	13/07/2023	>99.99	MOhm	Pass
Leakage	13/07/2023	0.12	mA	Pass
Load	13/07/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 11043 Description: LIGHT User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	13/07/2023			Pass
Earth Current	13/07/2023	25	A	Information
Earth	13/07/2023	<0.04	Ohm	Pass
Insulation	13/07/2023	>99.99	MOhm	Pass
Leakage	13/07/2023	0.14	mA	Pass
Load	13/07/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 11044 Description: LIGHT User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	13/07/2023			Pass
Earth Current	13/07/2023	25	A	Information
Earth	13/07/2023	<0.04	Ohm	Pass
Insulation	13/07/2023	>99.99	MOhm	Pass
Leakage	13/07/2023	0.14	mA	Pass
Load	13/07/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 11045 Description: LIGHT User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	13/07/2023			Pass
Earth Current	13/07/2023	25	A	Information
Earth	13/07/2023	<0.04	Ohm	Pass
Insulation	13/07/2023	>99.99	MOhm	Pass
Leakage	13/07/2023	0.13	mA	Pass
Load	13/07/2023	<0.05	kVA	Information

Overall: Pass

Asset ID: 1111L Description: 1111L User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	05/05/2023			Pass
Earth Current	05/05/2023	25	A	Information
Earth	05/05/2023	0.13	Ohm	Pass
Insulation	05/05/2023	66.31	MOhm	Pass
Polarity	05/05/2023			Pass

Overall: Pass

Total Tests: 94