

# Detailed Latest Test Results

From: 28/06/2023 To: 28/06/2024

Client: Corabar Entertainment		Site: 74 Moorlands		Location: AL7 4QG	
Asset ID: 1005L		Description: LEAD		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	06/05/2024			Pass	
Earth Current	06/05/2024	25	A	Information	
Earth	06/05/2024	0.05	Ohm	Pass	
Insulation	06/05/2024	>99.99	MOhm	Pass	
Polarity	06/05/2024			Pass	
Overall: Pass					
Asset ID: 10228L		Description: LEAD		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	06/05/2024			Pass	
Earth Current	06/05/2024	25	A	Information	
Earth	06/05/2024	0.06	Ohm	Pass	
Insulation	06/05/2024	>99.99	MOhm	Pass	
Polarity	06/05/2024			Pass	
Overall: Pass					
Asset ID: 10325		Description: 10325		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	06/05/2024			Pass	
Earth Current	06/05/2024	25	A	Information	
Earth	06/05/2024	0.05	Ohm	Pass	
Insulation	06/05/2024	>99.99	MOhm	Pass	
Polarity	06/05/2024			Pass	
Overall: Pass					
Asset ID: 10340		Description: LIGHT		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	06/05/2024			Pass	
Earth Current	06/05/2024	25	A	Information	
Earth	06/05/2024	<0.04	Ohm	Pass	
Insulation	06/05/2024	>99.99	MOhm	Pass	
Leakage	06/05/2024	0.13	mA	Pass	
Load	06/05/2024	<0.05	kVA	Information	
Overall: Pass					
Asset ID: 10341		Description: Light		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	06/05/2024			Pass	
Earth Current	06/05/2024	25	A	Information	
Earth	06/05/2024	0.04	Ohm	Pass	
Insulation	06/05/2024	>99.99	MOhm	Pass	
Leakage	06/05/2024	0.14	mA	Pass	
Load	06/05/2024	<0.05	kVA	Information	
Overall: Pass					
Asset ID: 10343		Description: Sound Control		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	06/05/2024			Pass	
Earth Current	06/05/2024	25	A	Information	
Earth	06/05/2024	0.07	Ohm	Pass	
Insulation	06/05/2024	>99.99	MOhm	Pass	
Leakage	06/05/2024	<0.1	mA	Pass	
Load	06/05/2024	<0.05	kVA	Information	
Overall: Pass					
Asset ID: 10344		Description: MIXER		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	06/05/2024			Pass	
Insulation	06/05/2024	>99.99	MOhm	Pass	
Touch Leakage	06/05/2024	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 10348		Description: Light		User: S JONES	
				Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status	
Visual	06/05/2024			Pass	
Earth Current	06/05/2024	25	A	Information	
Earth	06/05/2024	<0.04	Ohm	Pass	
Insulation	06/05/2024	>99.99	MOhm	Pass	

# Detailed Latest Test Results

From: 28/06/2023 To: 28/06/2024

Leakage	06/05/2024	0.16	mA	Pass
Load	06/05/2024	<0.05	kVA	Information
Overall: Pass				

Asset ID: 10349	Description: Light	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.12	mA	Pass
Load	06/05/2024	<0.05	kVA	Information
Overall: Pass				

Asset ID: 10360	Description: PSU	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Touch Leakage	06/05/2024	0.1	mA	Pass
Overall: Pass				

Asset ID: 10361	Description: PSU	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Touch Leakage	06/05/2024	<0.1	mA	Pass
Overall: Pass				

Asset ID: 10362	Description: Light	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.05	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.13	mA	Pass
Load	06/05/2024	<0.05	kVA	Information
Overall: Pass				

Asset ID: 10364	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	19/11/2023			Pass
Earth Current	19/11/2023	25	A	Information
Earth	19/11/2023	0.05	Ohm	Pass
Insulation	19/11/2023	>99.99	MOhm	Pass
Polarity	19/11/2023			Pass
Overall: Pass				

Asset ID: 1038L	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.07	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass
Overall: Pass				

Asset ID: 10393	Description: Light	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	19/11/2023			Pass
Earth Current	19/11/2023	25	A	Information
Earth	19/11/2023	<0.04	Ohm	Pass
Insulation	19/11/2023	>99.99	MOhm	Pass
Leakage	19/11/2023	<0.1	mA	Pass
Load	19/11/2023	<0.05	kVA	Information
Overall: Pass				

Asset ID: 10394	Description: LIGHT	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass

# Detailed Latest Test Results

From: 28/06/2023 To: 28/06/2024

Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.13	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10410	Description: PSU	User: S JONES	Test Instrument: X22-1286
-----------------	------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	20/03/2024			Pass
Insulation	20/03/2024	>99.99	MOhm	Pass
Touch Leakage	20/03/2024	<0.1	mA	Pass

Overall: Pass

Asset ID: 10411	Description: RADIO MIC RECEIVER	User: S JONES	Test Instrument: X22-1286
-----------------	---------------------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	20/03/2024			Pass
Insulation	20/03/2024	>99.99	MOhm	Pass
Touch Leakage	20/03/2024	<0.1	mA	Pass

Overall: Pass

Asset ID: 10507	Description: LEAD	User: S JONES	Test Instrument: X22-1286
-----------------	-------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.16	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass

Overall: Pass

Asset ID: 10508	Description: LEAD	User: S JONES	Test Instrument: X22-1286
-----------------	-------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	19/11/2023			Pass
Earth Current	19/11/2023	25	A	Information
Earth	19/11/2023	0.16	Ohm	Pass
Insulation	19/11/2023	>99.99	MOhm	Pass
Polarity	19/11/2023			Pass

Overall: Pass

Asset ID: 10540	Description: LIGHT	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.26	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10541	Description: LIGHT	User: S JONES	Test Instrument: X22-1286
-----------------	--------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.28	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10576	Description: LEAD	User: S JONES	Test Instrument: X22-1286
-----------------	-------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass

Overall: Pass

Asset ID: 10613	Description: SPEAKER	User: S JONES	Test Instrument: X22-1286
-----------------	----------------------	---------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass

# Detailed Latest Test Results

From: 28/06/2023 To: 28/06/2024

Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	<0.1	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10614	Description: SPEAKER	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	<0.1	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10616	Description: LIGHT	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.18	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10617	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass

Overall: Pass

Asset ID: 10751	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.05	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass

Overall: Pass

Asset ID: 1078L	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.07	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass

Overall: Pass

Asset ID: 10804	Description: SPEAKER	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	<0.1	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10806	Description: SPEAKER	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	<0.1	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

# Detailed Latest Test Results

From: 28/06/2023 To: 28/06/2024

Asset ID: 10855	Description: PSU	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Touch Leakage	06/05/2024	<0.1	mA	Pass
Overall: Pass				
Asset ID: 10856	Description: RADIO MIC RECEIVER	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Touch Leakage	06/05/2024	<0.1	mA	Pass
Overall: Pass				
Asset ID: 10857	Description: PSU	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Touch Leakage	06/05/2024	<0.1	mA	Pass
Overall: Pass				
Asset ID: 10858	Description: RADIO MIC RECEIVER	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Touch Leakage	06/05/2024	<0.1	mA	Pass
Overall: Pass				
Asset ID: 10888	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass
Overall: Pass				
Asset ID: 10890	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.09	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass
Overall: Pass				
Asset ID: 10897	Description: LIGHT	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	<0.1	mA	Pass
Load	06/05/2024	<0.05	kVA	Information
Overall: Pass				
Asset ID: 1089L	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass
Overall: Pass				
Asset ID: 10905	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.07	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass

# Detailed Latest Test Results

From: 28/06/2023 To: 28/06/2024

Polarity 06/05/2024 Pass  
Overall: Pass

Asset ID: 10918 Description: MIXER User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Touch Leakage	06/05/2024	<0.1	mA	Pass

Overall: Pass

Asset ID: 10971 Description: PSU User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Touch Leakage	06/05/2024	0.1	mA	Pass

Overall: Pass

Asset ID: 10972 Description: DJ CONTROLLER User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Touch Leakage	06/05/2024	<0.1	mA	Pass

Overall: Pass

Asset ID: 10975 Description: LIGHT User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	<0.1	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10976 Description: 10975 User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.38	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10977 Description: LIGHT User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.06	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.45	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10978 Description: LIGHT User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.45	mA	Pass
Load	06/05/2024	<0.05	kVA	Information

Overall: Pass

Asset ID: 10979 Description: LEAD User: S JONES Test Instrument: X22-1286

Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Polarity	06/05/2024			Pass

# Detailed Latest Test Results

From: 28/06/2023 To: 28/06/2024

Overall: Pass

Asset ID: 10980	Description: DJ CONTROLLER	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	06/05/2024		Pass
Insulation	06/05/2024	>99.99	MOhm Pass
Touch Leakage	06/05/2024	<0.1	mA Pass

Overall: Pass

Asset ID: 1099L	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	06/05/2024		Pass
Earth Current	06/05/2024	25	A Information
Earth	06/05/2024	0.04	Ohm Pass
Insulation	06/05/2024	>99.99	MOhm Pass
Polarity	06/05/2024		Pass

Overall: Pass

Asset ID: 11001	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	19/11/2023		Pass
Earth Current	19/11/2023	25	A Information
Earth	19/11/2023	0.07	Ohm Pass
Insulation	19/11/2023	>99.99	MOhm Pass
Polarity	19/11/2023		Pass

Overall: Pass

Asset ID: 11003	Description: Printer	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	19/11/2023		Pass
Earth Current	19/11/2023	25	A Information
Earth	19/11/2023	<0.04	Ohm Pass
Insulation	19/11/2023	>99.99	MOhm Pass
Leakage	19/11/2023	<0.1	mA Pass
Load	19/11/2023	<0.05	kVA Information

Overall: Pass

Asset ID: 11004	Description: Lead	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	19/11/2023		Pass
Earth Current	19/11/2023	25	A Information
Earth	19/11/2023	0.05	Ohm Pass
Insulation	19/11/2023	>99.99	MOhm Pass
Polarity	19/11/2023		Pass

Overall: Pass

Asset ID: 11006	Description: Touch Screen Monitor	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	19/11/2023		Pass
Insulation	19/11/2023	>99.99	MOhm Pass
Touch Leakage	19/11/2023	0.13	mA Pass

Overall: Pass

Asset ID: 11007	Description: PSU	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	19/11/2023		Pass
Insulation	19/11/2023	>99.99	MOhm Pass
Touch Leakage	19/11/2023	0.16	mA Pass

Overall: Pass

Asset ID: 11008	Description: Computer	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	19/11/2023		Pass
Insulation	19/11/2023	>99.99	MOhm Pass

Overall: Pass

Asset ID: 11010	Description: CAMERA PSU	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	19/11/2023		Pass
Insulation	19/11/2023	>99.99	MOhm Pass
Touch Leakage	19/11/2023	<0.1	mA Pass

# Detailed Latest Test Results

From: 28/06/2023 To: 28/06/2024

Overall: Pass

Asset ID: 11022	Description: PSU	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	19/11/2023		Pass
Insulation	19/11/2023	>99.99	MOhm Pass
Touch Leakage	19/11/2023	0.12	mA Pass

Overall: Pass

Asset ID: 11035	Description: VOLUME CONTROL	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	06/05/2024		Pass
Earth Current	06/05/2024	25	A Information
Earth	06/05/2024	0.07	Ohm Pass
Insulation	06/05/2024	>99.99	MOhm Pass
Leakage	06/05/2024	<0.1	mA Pass
Load	06/05/2024	<0.05	kVA Information

Overall: Pass

Asset ID: 11036	Description: RACK FAN	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	06/05/2024		Pass
Earth Current	06/05/2024	25	A Information
Earth	06/05/2024	0.06	Ohm Pass
Insulation	06/05/2024	>99.99	MOhm Pass
Leakage	06/05/2024	<0.1	mA Pass
Load	06/05/2024	<0.05	kVA Information

Overall: Pass

Asset ID: 11038	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	06/05/2024		Pass
Earth Current	06/05/2024	25	A Information
Earth	06/05/2024	0.05	Ohm Pass
Insulation	06/05/2024	>99.99	MOhm Pass
Polarity	06/05/2024		Pass

Overall: Pass

Asset ID: 11039	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	06/05/2024		Pass
Earth Current	06/05/2024	25	A Information
Earth	06/05/2024	0.04	Ohm Pass
Insulation	06/05/2024	>99.99	MOhm Pass
Polarity	06/05/2024		Pass

Overall: Pass

Asset ID: 11040	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	06/05/2024		Pass
Earth Current	06/05/2024	25	A Information
Earth	06/05/2024	<0.04	Ohm Pass
Insulation	06/05/2024	>99.99	MOhm Pass
Polarity	06/05/2024		Pass

Overall: Pass

Asset ID: 11041	Description: LEAD	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	06/05/2024		Pass
Earth Current	06/05/2024	25	A Information
Earth	06/05/2024	<0.04	Ohm Pass
Insulation	06/05/2024	>99.99	MOhm Pass
Polarity	06/05/2024		Pass

Overall: Pass

Asset ID: 11042	Description: LIGHT	User: S JONES	Test Instrument: X22-1286
Test Type	Date	Result	Unit Status
Visual	06/05/2024		Pass
Earth Current	06/05/2024	25	A Information
Earth	06/05/2024	<0.04	Ohm Pass
Insulation	06/05/2024	>99.99	MOhm Pass



# Detailed Latest Test Results

From: 28/06/2023 To: 28/06/2024

Leakage	06/05/2024	0.21	mA	Pass
Load	06/05/2024	<0.05	kVA	Information
Overall: Pass				

Asset ID: 11043	Description: LIGHT	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.21	mA	Pass
Load	06/05/2024	<0.05	kVA	Information
Overall: Pass				

Asset ID: 11044	Description: LIGHT	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.21	mA	Pass
Load	06/05/2024	<0.05	kVA	Information
Overall: Pass				

Asset ID: 11045	Description: LIGHT	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	<0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	0.21	mA	Pass
Load	06/05/2024	<0.05	kVA	Information
Overall: Pass				

Asset ID: 11046	Description: POWER CONDITIONER	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Earth Current	06/05/2024	25	A	Information
Earth	06/05/2024	0.04	Ohm	Pass
Insulation	06/05/2024	>99.99	MOhm	Pass
Leakage	06/05/2024	<0.1	mA	Pass
Load	06/05/2024	<0.05	kVA	Information
Overall: Pass				

Asset ID: 11047	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	19/11/2023			Pass
Earth Current	19/11/2023	25	A	Information
Earth	19/11/2023	0.05	Ohm	Pass
Insulation	19/11/2023	>99.99	MOhm	Pass
Polarity	19/11/2023			Pass
Overall: Pass				

Asset ID: 11048	Description: LEAD	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	19/11/2023			Pass
Earth Current	19/11/2023	25	A	Information
Earth	19/11/2023	0.04	Ohm	Pass
Insulation	19/11/2023	>99.99	MOhm	Pass
Polarity	19/11/2023			Pass
Overall: Pass				

Asset ID: 11049	Description: LIGHT CONTROL	User: S JONES	Test Instrument: X22-1286	
Test Type	Date	Result	Unit	Status
Visual	06/05/2024			Pass
Insulation	06/05/2024	76.06	MOhm	Pass
Touch Leakage	06/05/2024	<0.1	mA	Pass
Overall: Pass				

Total Tests: 72